

Mr. Michael Berkoff Remedial Project Manager U.S. EPA Superfund Division/Region 5 Mail Code SR-6J 77 West Jackson Blvd. Chicago, Illinois 60604-3590



ARCADIS of New York, Inc 6723 Towpath Road P O Box 66 Syracuse New York 13214-0066 Tel 315 446 9120 Fax 315 445 9161 www.arcadis-us.com

ENVIRONMENT

Date: December 6, 2012

Contact: Patrick N. McGuire

Phone: 315.671.9233

Pat.McGuire@arcadis-us.com

Our ref: B0064581.0003.00672

Subject

Willow Boulevard/A-Site Groundwater Monitoring Program Kalamazoo, Michigan

Dear Mr. Berkoff:

Georgia-Pacific, LLC (Georgia-Pacific) and ARCADIS, on behalf of Georgia-Pacific, have recently engaged with the Michigan Department of Environmental Quality (MDEQ) and the U.S. Environmental Protection Agency (USEPA) regarding post-closure monitoring requirements for the Willow Boulevard/A-Site Operable Unit (WB/A OU) of the Allied Paper, Inc./Portage Creek/Kalamazoo River Superfund Site (Site). In a September 13th conference call and at a October 22, 2012 meeting in Lansing, ARCADIS presented options for demonstrating compliance with Michigan's Natural Resources and Environmental Protection Act, 1994 PA 451, Part 201 (Part 201), in particular a finding of *de minimis* potential contribution of PCB at the groundwater surface water interface (GSI) adjacent to the WB/A OU. ARCADIS also described proposed performance monitoring activities to comply with the Record of Decision and Consent Decree for the WB/A OU. The available data and the hypothetical PCB discharge estimates demonstrate that the WB/A OU has a *de minimis* effect on the groundwater-surface water interface with respect to polychlorinated biphenyls (PCBs)

We are awaiting concurrence from MDEQ with our view that the WB/A OU is a *de minimus* situation with respect to potential PCB influences at the GSI and in the Kalamazoo River. With MDEQ's concurrence, we will then submit a request for a formal determination that Part 201 requirements have been met by the *de minimis* demonstration.

Under the current Part 201 rules, the extensive Vertical Aquifer Sampling (VAS) characterization of the upper aquifer previously requested by MDEQ is not necessary, or warranted in this case. We look forward to discussing an appropriate approach to design and installation of a groundwater monitoring well network.

At the request of MDEQ, with this letter we provide available hydrogeologic information for the WB/A OU that is relevant to selection of monitoring well screen depth intervals near the groundwater surface:

ARCADIS

Mr. Michael Berkoff December 6, 2012

Hydrogeologic Information

Hydrogeologic data available for the site support an understanding that groundwater flow in the shallow aquifer above the silt unit is dominated by lateral flow from upland areas toward the river.

- Attachment 1 Cross Section Location Map presents locations of wells and borings used to develop the cross-sectional groundwater flow diagrams that are presented in Attachment 2.
- Attachment 2 Cross Sections B-B', C-C', and D-D' present geology and groundwater flow diagrams from the upland to the river, through the Willow Boulevard and A-Site disposal areas, respectively. The flow diagrams indicate predominant horizontal groundwater flow beneath the disposal areas toward the river. These diagrams support a monitoring well network design that focuses on shallow groundwater.
- Attachment 3 Logs for Soil Borings and Monitoring Wells at WB/A OU reference detailed descriptions of site geology and well screen depth intervals.
- Attachment 4 Parker-Hannifin Horizontal Plume Maps figures showing
 monitoring well locations and TCE and cis-1,2-DCE groundwater plumes
 associated with Parker-Hannifin facility. The groundwater plume extends from
 the Parker-Hannifin site approximately 1 mile north to the WB/A OU. The figures,
 which also show depth of impact to groundwater, demonstrate lateral
 groundwater flow to the river.
- Attachment 5 Log for Parker-Hannifin Monitoring Well Cluster GS-MW-OFF-10(S, M, D) well cluster located along Willow Boulevard between Lamont and Willis avenues. Clustered wells are installed to depths of approximately 20, 38, and 72 feet below ground surface (bgs). The boring log for this location shows a good correlation with the WB/A OU site geology as mapped from soil borings, and extends quite a bit deeper to bedrock at 74 feet bgs. The deepest well in the cluster is screened below a confining silt unit that separates shallow and deep aquifers.
- Attachment 6 Historical Measurements of Groundwater Levels at Parker-Hannifin Monitoring Well Cluster GS-MW-OFF-10(S, M, D) data indicate that a neutral to slightly downward vertical gradient typically exists in the shallow aquifer above the confining silt unit at this location upgradient of the WB/A OU. At this well cluster, detections of vinyl chloride and several other volatile compounds are observed only in the intermediate depth (M) well, which is screened approximately 38 feet below the water table. Given the 1 mile distance from the Parker-Hannifin property, these data are consistent with the WB/A OU site conceptual model in which groundwater flow is predominated by lateral flow toward the river. The water elevation data for the deep aquifer, represented by

Monitoring Well GS-MW-OFF-10D, indicate there is an upward gradient between the deep and shallow aquifers.

Attachment 7 – A-Site Sheetpile Design Drawings – drawings detailing the
alignment and design elevations of the sheetpile wall at A-Site relative to the
edge of the disposal area and the approximate median and 100-year flood
elevations of the river. The sheetpile bottom (737 ft AMSL) may be of use in
considering design of the groundwater monitoring network.

With the information provided herein and in previous reports, meetings, and presentations, we reiterate our request for USEPA's and MDEQ's feedback on our demonstration that PCB in groundwater presents a de minimis effect on the Kalamazoo River, consistent with Part 201. As discussed during our April 2012 meeting, GP is willing to perform an appropriate VAS program for purposes of selecting groundwater monitoring well screen depths - focused the shallow aquifer zones most likely to intersect groundwater flow paths in close proximity to the bottom of the landfill. We see no technical basis or need to pursue deeper zones, not only based on the available site data but also in consideration of the de minimus condition with respect to PCBs. We are interested in hearing the agencies' thoughts on what level of effort is needed in this regard prior to our planned December 19th meeting in Kalamazoo. We are hopeful we can agree upon the basic components of the groundwater monitoring network construction and analytical program at our planned meeting. Should you have any questions relating to the information presented or if ARCADIS can provide any additional assistance, please feel free to call me at 312.671.9233 or Garry Griffith at 734.735.0780 at your convenience.

Sincerely,

ARCADIS of New York, Inc.

Patrick N. McGuire

Project Coordinator/Principal Environmental Engineer

Attachments (7)

Copies

Michael Berkoff, USEPA John Bradley, MDEQ Anne Couture, MDEQ Daria Devantier, MDEQ Steven Hoin, MDEQ David Kline, MDEQ Kristi Zakrzewski, MDEQ Jeff Keiser, CH2M HILL

ARCADIS

Mr. Michael Berkoff December 6, 2012

Garry Griffith, Georgia-Pacific Michael Erickson, ARCADIS Daniel O'Neill, ARCADIS

> Page: 4/5



Mr. Michael Berkoff December 6, 2012

Blind Courtesy Copies: Lisa Coffey, ARCADIS Douglas K. Cowin, ARCADIS



Cross Section Location Map

LEGEND

⊞AMW-4 PRE-RI MONITORING WELL

MONITORING WELL OR CLUSTER INSTALLED IN 1993

VB-1 BORING INSTALLED IN 1993

GEO-1 GEOTECHNICAL BORING INSTALLED IN 1993

P-2D PIEZOMETER INSTALLED IN 1993

SW-1 SURFACE WATER SAMPLE, INSTALLED IN 1993

RG-1 RIVER GAUGE STATION INSTALLED IN 1993

ELEVATION CONTOUR

(NGVD 1929)


EDGE OF WATER OR DRAINAGE CHANNEL

UNPAVED ROAD/TRAIL

EXISTING SHEETPILE WALL

NOTES:

- UNLESS OTHERWISE INDICATED ALL SAMPLE LOCATIONS SURVEYED BY WADE-TRIM INC. OCTOBER 1993 THROUGH AUGUST 1996. SAMPLES ARN-1 THROUGH ARN-5 AND RN-1 THROUGH WRN-5 WERE SURVEYED BY BBL JULY 1993.
- TOPOGRAPHIC MAPPING PRODUCED USING PHOTOGRAMMETRIC METHODS BY LOCKWOOD, INC. FROM AERIAL PHOTOGRAPHY FLOWN APRIL 1991. TOPOGRAPHIC CHANGES AFTER APRIL 1991 ARE NOT SHOWN.
- SAMPLE RESULTS AS REPORTED BY AQUATEC, INC. 1995 AND 1996.



KALAMAZOO RIVER STUDY GROUP ALLIED PAPER, INC./PORTAGE CREEK/KALAMAZOO RIVER SUPERFUND SITE

GEOLOGIC CROSS-SECTION LOCATION MAP




FIGURE


ENVCADISYRACUSENCTB0008458100000000000000064581G02.DWG LAYOUT: 1 SAVED: 224/2011 3:01 PM ACADVER: 18.05 (LMS TECH) PAGESETUP: — PLOT

EFS: IMAGES: PROJE



Cross Sections B-B', C-C', D-D'







KALAMAZOO RIVER STUDY GROUP ALLIED PAPER, INC./PORTAGE CREEK/KALAMAZOO RIVER SUPERFUND SITE WILLOW BOULEVARD/A-SITE OU

GEOLOGIC CROSS-SECTIONB-B' WITH GROUNDWATER FLOW NET NOVEMBER 10, 2000









KALAMAZOO RIVER STUDY GROUP
ALLIED PAPER, INC./PORTAGE CREEK/KALAMAZOO RIVER
SUPERFUND SITE
WILLOW BOULEVARD/A-SITE OU

GEOLOGIC CROSS-SECTION C-C' WITH GROUNDWATER FLOW NET **NOVEMBER 10, 2000**








KALAMAZOO RIVER STUDY GROUP
ALLIED PAPER, INC./PORTAGE CREEK/KALAMAZOO RIVER
SUPERFUND SITE
WILLOW BOULEVARD/A-SITE OU

GEOLOGIC CROSS-SECTION D-D' WITH GROUNDWATER FLOW NET **NOVEMBER 10, 2000**





Logs for Soil Borings and Monitoring Wells at WB/A OU



LEGEND ⊞AMW-4 PRE-RI MONITORING WELL ₩WW-1A MONITORING WELL OR CLUSTER INSTALLED IN 1993 REPLACEMENT MONITORING WELL INSTALLED IN 1996 BORING INSTALLED IN 1993 GEOTECHNICAL BORING INSTALLED IN 1993 -OP-2D PIEZOMETER INSTALLED IN 1993 △DCD-SW SURFACE WATER SAMPLE, 1993 INVESTIGATION ⊕RG-1 RIVER GAUGE STATION INSTALLED IN 1993 WB-5 AIR SAMPLER INSTALLED IN 1993 \boxtimes ELEVATION CONTOUR (NGVD 1929) EDGE OF WATER OR DRAINAGE CHANNEL ----- UNPAVED ROAD/TRAIL KPT-5 SEDIMENT PROBING TRANSECT



NOTES:

- UNLESS OTHERWISE INDICATED ALL SAMPLE LOCATIONS SURVEYED BY WADE—TRIM INC. OCTOBER 1993 THROUGH AUGUST 1996. SAMPLES ARN-1 THROUGH ARN-5 AND WRN-1 THROUGH WRN-5 WERE SURVEYED BY BBL JULY 1993.
- TOPOGRAPHIC MAPPING PRODUCED USING PHOTOGRAMMETRIC METHODS BY LOCKWOOD, INC. FROM AERIAL PHOTOGRAPHY FLOWN APRIL 1991. KALAMAZOO RIVER SOUTH BANK, EAST OF DAVIS CREEK REWSED PER CURRENT CONDITIONS. ADDITIONAL TOPOGRAPHIC CHANGES AFTER APRIL 1991 ARE NOT SHOWN.
- 3. ALL LOCATIONS ARE APPROXIMATE.

KALAMAZOO RIVER STUDY GROUP
ALLIED PAPER, INC./PORTAGE CREEK/KALAMAZOO RIVER SUPERFUND SITI
REMEDIAL INVESTIGATION/FOCUSED FEASIBILITY STUDY
WILLOW BOULEVARD/A—SITE OU

SAMPLE LOCATIONS (PRE-RI TO 1996)

X: 64582X02 I: OFF=1*, WBL*, REF P: FIG-2-3 2/22/01 SYR-54-RLP HSB DJP 64581500\64581G01.DWG

Georgia-Pacific LLC Allied Paper, Inc./Portage Creek/Kalamazoo River Superfund Site

Groundwater Elevations at Parker Hannifin Well Cluster on Willow Boulevard

| Date | GS-MW-OFF-10S | | | GS-MW-OFF-10M | | | GS-MW-OFF-10D | | | Difference | Vertical |
|----------|----------------------------|-----------------------------|------------------------------------|----------------------------|-----------------------------|------------------------------------|----------------------------|-----------------------------|------------------------------------|---|---|
| | TOC Elevation (feet) | Depth to Water (feet) | Water Level Elevation (feet) | TOC Elevation (feet) | Depth to Water (feet) | Water Level Elevation (feet) | TOC Elevation (feet) | Depth to Water (feet) | Water Level Elevation (feet) | Between 10S & 10M Elevation (feet) | Gradient Between 10S & 10M (ft/ft) |
| 9/23/05 | 760.51 | 3.69 | 756.82 | 760.52 | 3.81 | 756.71 | 760.52 | 2.61 | 757.91 | -0.11 | -0.006 |
| 1/16/06 | 760.51 | 2.00 | 758.51 | 760.52 | 2.16 | 758.36 | 760.52 | 0.50 | 760.02 | -0.15 | -0.008 |
| 5/15/06 | 760.51 | 2.80 | 757.71 | 760.52 | 1.34 | 759.18 | 760.52 | 0.00 | 760.52 | 1.47 | 0.080 |
| 9/11/06 | 760.51 | 3.10 | 757.41 | 760.52 | 3.24 | 757.28 | 760.52 | 1.58 | 758.94 | -0.13 | -0.007 |
| 1/22/07 | 760.51 | 1.40 | 759.11 | 760.52 | 1.48 | 759.04 | 760.52 | 0.00 | 760.52 | -0.07 | -0.004 |
| 7/16/07 | 760.51 | 3.75 | 756.76 | 760.52 | 3.82 | 756.70 | 760.52 | 2.20 | 758.32 | -0.06 | -0.003 |
| 1/28/08 | 760.51 | 1.73 | 758.78 | 760.52 | 1.79 | 758.73 | 760.52 | 0.00 | 760.52 | -0.05 | -0.003 |
| 9/3/08 | 760.51 | 3.63 | 756.88 | 760.52 | 3.70 | 756.82 | 760.52 | 1.78 | 758.74 | -0.06 | -0.003 |
| 3/24/09 | 760.51 | 1.12 | 759.39 | 760.52 | 1.12 | 759.40 | 760.52 | 0.00 | 760.52 | 0.01 | 0.001 |
| 9/21/09 | 760.51 | 2.96 | 757.55 | 760.52 | 3.03 | 757.49 | 760.52 | 1.52 | 759.00 | -0.06 | -0.003 |
| 3/22/10 | 760.51 | 1.48 | 759.03 | 760.52 | 1.52 | 759.00 | 760.52 | 0.00 | 760.52 | -0.03 | -0.002 |
| 12/15/10 | 760.51 | 2.48 | 758.03 | 760.52 | 2.53 | 757.99 | 760.52 | 1.22 | 759.30 | -0.04 | -0.002 |
| 12/20/10 | 760.51 | | - | 760.52 | 2.73 | 757.79 | 760.52 | 1.44 | 759.08 | | |
| 6/7/11 | 760.51 | | _ | 760.52 | 1.02 | 759.50 | 760.52 | 0.00 | 760.52 | - | |
| 8/30/11 | 760.51 | 0.88 | 759.63 | 760.52 | 2.91 | 757.61 | 760.52 | 1.29 | 759.23 | -2.02 | -0.110 |
| 3/26/12 | 760.51 | 1.75 | 758.76 | 760.52 | 1.71 | 758.81 | 760.52 | 0.90 | 759.62 | 0.05 | 0.003 |

Notes:

A negative vertical gradient indicates a downward flow potential.

The separation between the mid-point of the S & M well screens is 18.3 feet.

Data provided in May 9, 2012 email from Geosyntec to Doug Cowin.

The depth of monitoring well GS-MW-OFF-10S is 19.5 feet, the depth of GS-MW-OFF-10M is 37.8 feet, and the depth of GS-MW-OFF-10D is 72.3 feet.



A-Site Sheetpile Design Drawings

GEORGIA-PACIFIC CORPORATION WILLOW BOULEVARD / A-SITE OPERABLE UNIT A-SITE EROSION CONTROL SYSTEM CONSTRUCTION CERTIFICATE KALAMAZOO, MICHIGAN

PREPARED FOR: GEORGIA-PACIFIC CORPORATION


KALAMAZOO, MICHIGAN

PREPARED BY: RMT, INC., MICHIGAN ANN ARBOR, MICHIGAN

DATE: AUGUST 1998



MICHIGAN STATE MAP





SITE LOCATION MAP


DRAWING INDEX


| SHEET NO. | SHEET TITLE | | | | | | |
|-----------|---------------------------------|--|--|--|--|--|--|
| 1 | INDEX / TITLE SHEET | | | | | | |
| 2 | EXISTING CONDITIONS | | | | | | |
| 3 | SHEETPILE WALL PLAN AND PROFILE | | | | | | |
| 4 | DETAILS | | | | | | |
| 5 | DETAILS | | | | | | |
| 6 | DETAILS | | | | | | |











- KMI,